



***Client:*** *Alternative Petroleum Services*

***Date:*** *January 24, 2026*

***Subject Property:*** *59 La Grange St, Raritan, NJ*

Oil Tank Sweep Premier LLC performed a visual inspection and physical sweep of the above referenced property to identify existing vent pipes, fill pipes and fuel distribution lines for an underground storage tank (UST). No vent pipes, fill pipes or fuel distribution lines were found during the inspection of the property.

Utilizing electronic metal detection equipment and Ground Penetrating Radar (Fisher TW-6 & LMX200e), the grounds were swept searching for any buried metallic objects representing a UST. The detection equipment utilized is capable of locating a metallic object up to a depth of five feet.

The property was swept around the empty lot. No metal anomalies consistent with the size of an underground storage tank were identified during the oil tank sweep.

If you have any questions about this report please feel free to contact us.

A handwritten signature in black ink that reads "Eric Hanson".

Eric Hanson

908-246-0852

Oil Tank Sweep Premier LLC

2 Mountain Brook Ln, Glen Gardner, NJ 08826

Terms and Conditions: Areas not accessible to the magnetic locator due to locational variabilities, dense vegetation, denied access, structural blockage, outdoor furniture or AC units at the time the sweep was performed are excluded from this report. The methods used at this site have been used successfully at many sites to locate underground storage tanks and drums. There can be no guarantee, however, that every target will be

detected at a particular sight due to listed variables. We are not responsible for the removal of any metallic areas other than an oil/gas tank if they are found at a later date within the 30ft perimeter. Subsurface conditions (e.g. rebar/wire mesh under concrete, metal siding, foundations, structures, soil quality and others) may prevent some or all geophysical locating methods from working properly. There are no refunds after the work is completed and the job is paid for unless a oil/gas tank is later found and you've taken possession of said property, in which case it will be removed/remediated and paid for at our cost. By accepting this report you agree to all the above statements and terms and conditions. This document and guarantee is only valid for the paid customer above and is not transferable to the next owner.

---